



GROUP
BOD

MODEL
2018MY
Stinger (CK)

NUMBER
178 (Rev 1, 1/30/2018)

DATE
December 2017

TECHNICAL SERVICE BULLETIN

SUBJECT: SERVICE ACTION: RATTLE NOISE
FROM TAILGATE (SA322)

* NOTICE

This bulletin has been revised to include additional information. New/revised sections of this bulletin are indicated by a black bar in the margin area.

This bulletin provides the procedure to adjust the overslam bumper and install a guide bumper mounting kit on some 2018MY Stinger (CK) vehicles produced from September 21, 2017 through January 4, 2018, which may exhibit rattle noise while driving, especially over bumps. Follow the procedure outlined in this bulletin to adjust the overslam bumpers and install a guide bumper mounting kit. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.



* NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer request to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA322.

File Under: <Body>

Circulate To: ☒ General Manager ☒ Service Manager ☒ Parts Manager
☒ Service Advisors ☒ Technicians ☒ Body Shop Manager ☒ Fleet Repair