

*** * TECHNICAL INFORMATION NOTICE * ***

DATE: February 14, 2018
TO: Mitsubishi Motors US & Puerto Rico Dealer Service and Parts Managers
RE: Starting Engine with IOD Disengaged – 2018 Eclipse Cross
TIN NO. TIN-18-42B-001

AFFECTED VEHICLES: 2018 Eclipse Cross equipped with FAST key and One Touch Start System (OSS)

PURPOSE

When the IOD fuse is disengaged on a new 2018 Eclipse Cross with FAST key and One Touch Start System (OSS), there is a unique procedure to start the engine. Use the following steps during PDI or anytime the IOD fuse is disengaged, also shown in the video linked below, to start the engine with the FAST key and engine start switch.

1. Vehicle status: IOD disengaged.
2. Press the engine start switch once. The green light in the switch begins to flash.
3. Place the FAST key transmitter on top of the engine start switch for 1 – 2 seconds, making sure to center the key over the switch as shown.



4. When FAST key is removed, the green light in the engine switch should be solid (not flashing).
5. Depress brake pedal and press the engine start switch to start the engine.



To view a short video demonstrating the engine starting procedure, click on this link:

[Link to video](#)