



Service Bulletin

15-17

Section

Lighting - 34

Description

Low Beam Headlamp Bulb Diagnosis (Inspect Bulb and Connector)

Release Date

2/9/2018

Introduction

Peterbilt has determined that certain headlights on Models 579 and 587 vehicles have unnecessarily been replaced during a low beam headlamp diagnosis. See the attached technical bulletin below for specific details and procedures.

This bulletin does not apply to (HID) High Intensity Discharge headlights.

Resolution

Inspect the bulb and bulb connector for damage or discoloration and follow the procedures attached below.

Warranty

Through Standard Warranty Peterbilt will pay for parts at dealer net plus applicable mark-up and labor.

- 0.8 hours labor to inspect and if needed replace the headlamp connector. File a quick claim 15-17
- File a long form claim for extraordinary circumstances, a quick claim must be filed first.

For Field...	Enter...
Failure Location	034-001-003
Failure Type	180
Claim Type	N
SRT 034-A96	0.4 x 2 = 0.8 hours labor to inspect and if needed repair the headlight connector.

Parts

Parts are available from PACCAR Parts.

Quantity	Part Number	Description
2	P74-6014	KIT- H11 LOW BEAM CONNECTOR
2	HT92500	2 pieces of 6 in. long, 1/4 in. diameter heat shrink
4	3M Scotchlock M14BC or equivalent	14-16 AWG Unsealed butt splice (source locally)

Take off part disposition: Destroy take off parts

Procedure

See the attached repair instructions for the specific headlight configuration.

[15-17 Headlight Connector Inspection and Repair Instructions](#)

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2018 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).