

[Next Unread Message](#)[View Message](#)

<b>Sent on</b>	03	20	2018	<b>Expires on</b>	04	02	2018
----------------	----	----	------	-------------------	----	----	------

<b>From</b>	Parts and Service Division
-------------	----------------------------

<b>Subject</b>	Request for Parts: 2017-2018 CR-V Radar Misaligned with DTC P2583-76 Stored
----------------	---

**PRIORITY/ACTION REQUIRED**

To: All Honda Service Managers/Advisors  
 From: Technical Research & Support Group  
 RE: Request for Parts: 2017-2018 CR-V Radar Misaligned with DTC P2583-76 Stored

This message is solely directed to Honda dealership personnel; please handle accordingly.  
 Print this *i/N* message and provide a copy to the Shop Foreman and all Service Advisors.

**Background**

American Honda Motor Co., Inc. (AHM) is investigating certain 2017-2018 CR-Vs with a customer complaint of various warning lights such as the brake system, lane departure, ACC & forward collision warning illuminated on the dash with the DTC P2583-76 (Temporary stop of Integrated Driver System – Misalignment Millimeter Wave Radar) stored. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind except to confirm conditions stated in the Qualifiers below before calling TRS.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirement:

1. VIN must start with 2HK.
2. Customer reported one or more of the warning lights.
3. DTC P2583-76 must be stored.
4. Inspect the radar alignment clips for proper setting. If the clips are broken or damaged, take pictures then call TRS.

**Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.