Next Unread Message

View Message

| Sent on | 04 | 06 | 2018 | Expires on | 04 | 20 | 2018 | | |
|---------|--|----|------|------------|----|----|------|--|--|
| _ | | , | | | | | | | |
| From | Parts and Service Division | | | | | | | | |
| Subject | Request for Visit: 2018 Odyssey Fuel Lid Inop | | | | | | | | |
| | Trequestion visit. 2010 odyssey i dei Eld Inop | | | | | | | | |

PRIORITY/ACTION REQUIRED

To: All Honda Service Managers/Advisors
From: Technical Research & Support Group
RE: Request for Visit: 2018 Odyssey Fuel Lid Inop

This message is solely directed to Honda dealership personnel; please handle accordingly. Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

Background

American Honda Motor Co., Inc. (AHM) is investigating certain 2018 Odysseys with a customer complaint of the fuel lid not opening when pushed. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

- 1. Must be able to duplicate the issue.
- 2. No repair has been attempted for this issue.

Action Required

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.