

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

RECALL SERVICE BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	RSB #
3/22/2018	2018	515
MODEL		
Bay Star Sport ☐	Ventana ☐	Essex ☒
Bay Star ☐	Dutch Star ☐	King Aire ☐
Canyon Star ☐	Mountain Aire ☐	New Aire ☐
Ventana LE ☐	London Aire ☐	Other ☐
DESCRIPTION		
Newmar Corporation has decided that a defect relating to motor vehicle safety exists in specific motorhomes. NHTSA #18V 144, TC # 2018-109 Issue: On certain motorhomes, the tail lights may become loose and could separate from the vehicle. If the tail lights separate, drivers following the motorhome may become unaware of the motorhome driver's intentions, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers should secure the tail lights using the correct anchorage hardware. Affected Units: Refer to the attached population list for specific coach and VIN numbers.		
RECOMMENDED ACTION		
Contact your Service Account Manager at Newmar for authorization and parts, and follow the attached work instructions to secure the tail light assemblies. Flat Rate Code: RSB 515 Labor Time: .3 hr. <u>Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.</u>		