

Reference	SSM73800
Models	Discovery / L462 Range Rover / L405 Range Rover Sport / L494
Title	Wheel Speed Sensor harness misrouted - 18MY
Category	Chassis
Last modified	21-Mar-2018 00:00:00
Symptom	301000 Service Brake System
Attachments	Correct Routing 1.pdf Correct Routing 2.pdf Correct Routing.pdf

Content

Models affected:
L494 – 18MY only
L405 – 18MY only
L462 – 18MY only

Issue

L405, L494 and L462 wheel speed sensor harness routing changed for 18MY. The routing shown in Topix is incorrect

Cause

Topix workshop manual incorrect

Action

See attached pictures of both left hand and right hand wheels and CAD drawings for correct routing while Topix is being updated

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.