

Reference	SSM73781
Models	F-PACE / X761 XE / X760 XF / X260
Title	Software update required following Image Processing Module A replacement
Category	Electrical
Last modified	01-Mar-2018 00:00:00
Symptom	206000 Warning Indicators
Content	<p><u>Note</u> Affects XE 16 and 17 model year and XE, XF and F Pace 18my IPMA only</p> <p><u>Issue</u> The Image Processing Module A (IPMA)has not been updated to latest level software.</p> <p><u>Cause</u> Incorrect software level in IPMA</p> <p><u>Action</u> If there is a requirement to replace Image Processing Module A, please ensure that the latest level software is installed. The SRO time for this download is Image Processing Module A(IPMA) 86.56.96 0.2 hours Requires SDD 152.05.001 or later for XE 16my and 17my Requires Pathfinder 140 or later for 18my XE, XF, FPace</p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>