

F-TYPE
18MY with
Ingenium
AJ20P

A customer may
complain of a
coolant leak from
the vehicle.

If diagnosis leads to identification of the upper radiator hose breather pipe
leaking due to damage to the pipe close to the turbocharger, please raise a TA.
This topic is under investigation and repair guidance will be offered via the TA.



TBD