

E-PACE

A Customer may report a knocking type noise from the rear of the vehicle.

An issue has been identified on certain vehicles where the rear suspension stabilizer bar bushes have been manufactured away from the required specification, causing insufficient clearance between the rear suspension stabilizer bar and the rear suspension left coil spring. Replacement of the sway bar will be required.

H082NAS1