

Clattering noise from underbody/exhaust system, vibrations after cold start

Topic number	LI49.00-P-067579
Version	1
Function group	49.00 General
Date	01-10-2018
Validity	Model 213.#88//#89
Reason for change	
Reason for block	

Complaint:

Clattering noise from underbody/exhaust system, vibrations after cold start.

Note:

When the engine is warm, the noises may not be as audible.

Cause:

Reinforcement under exhaust system in vehicle center.

Remedy:

Check installed reinforcement

SPECIFIED: Bent reinforcement with part number A 213 619 2500 (see pictures in attachment)

Attachments	
File	Description
082557.jpg	Specified status of bent reinforcement
081800.jpg	Specified status of reinforcement part number

Symptoms

Chassis/suspension / Noises / Knocks

Chassis/suspension / Noises / Thumping

Power generation / Engine noise / Knocking/clacking

Chassis/suspension / Noises / Vibrates

Power generation / Engine noise / Clattering

Power transmission / Noises / Throttle lift-off clunking noise

Power generation / Exhaust system / Noises / Knocks

Chassis/suspension / Noises / Clattering

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
-------------	-----	-----	-------------	----------	------	-----

XENTRY TIPS

A 213 619 25 00		Reinforcement	1	As required	X
N 910143 010014		Bolt	4	As required	X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			6105R **	Please quote TIPS document number in dealer text

Validity		
Vehicle	Engine	Transmission
E (213) - 213.088	*	*
E (213) - 213.089	*	*
E (213) - 213.288	*	*
E (213) - 213.289	*	*

Attachments

082557.jpg:



081800.jpg:

