

Floor covering on front passenger side at center console too short

Topic number	LI68.30-P-067589
Version	1
Function group	68.30 Coverings, trim
Date	01-12-2018
Validity	C238 / A238 Up to production date 15.06.2017
Reason for change	
Reason for block	

Complaint:

Floor covering on front passenger side at center console too short.

Attachments	
File	Description
pic 1.jpg	Overview of damage profile
pic 2.jpg	Detailed view of damage profile

Cause:

Floor covering on front passenger side at center console was built too short.

Remedy:

Replace floor covering on front passenger side.

Symptoms
Body / Interior equipment / Floor covering / Bad fitting

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 238 680 61 00			Floor covering on front passenger side at left	1	For RHD vehicles	X
A 238 680 62 00			Floor covering on front passenger side at right	1	For LHD vehicles	X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note

XENTRY TIPS

68-4018	REPLACE FLOOR COVERING ON FRONT PASSENGER SIDE (RIGHT)	8 AW	68R01 42	
68-4018	REPLACE FLOOR COVERING ON FRONT PASSENGER SIDE (LEFT)	8 AW	68C01 42	

Attachments

pic 1.jpg:



pic 2.jpg:



XENTRY TIPS
