

T57 Removal of Electric Side Step

Topic number	LI72.16-N-067640
Version	1
Function group	72.16 Sliding doors
Date	01-26-2018
Validity	Sprinter 906.xxx
Reason for change	
Reason for block	

Complaint:

Customer requests removal of electric side step (T57).

Cause:

Customer requests to have the factory installed electric side step removed from the vehicle.

Remedy:

Remove code T57 (via an XSF ticket) from VeDoc then SCN code the following control units.

1. Instrument Cluster
2. EZS
3. PSM

Note: Depending on the application the vehicle may have other PSM programs installed on it. Make sure to make a copy of the program that's currently installed on the PSM before you re-SCN code it. This is best practice to prevent additional functions from being disabled.

* Please see attachment "PSM Upload" for instructions on uploading and saving PSM files

Attachments	
File	Description
PSM upload.pdf	PSM Upload

Symptoms
Overall vehicle / Complete vehicle / Modified to

Control unit/fault code		
Control unit	Fault code	Fault text
PSMParameterizable special module (PSM906)	-	-

XENTRY TIPS

Validity		
Vehicle	Engine	Transmission
Sprinter III	*	*