



SI B71 02 18  
Tools and Accessories (Engine-Chassis)

March 2018  
Technical Service

## DELIVERY STOP: REPLACE UNDERHOOD EMISSIONS LABEL

New information provided by this revision is preceded by this symbol .

This Service Information bulletin replaces SI B71 02 18 **dated March 2018**.

### What's New:

- Warranty information added

## MODEL

|                |  |  |  |
|----------------|--|--|--|
| F30 (3 Series) |  |  |  |
|----------------|--|--|--|

Produced between November 14, 2017 and February 11, 2018.

## SITUATION

A Delivery Stop has been issued (effective March 2, 2018) on Model Year 2018 BMW 3 Series vehicles that have been produced from November 14, 2017 – February 11, 2018. The affected vehicles were equipped with an incorrect **emissions label** which must be replaced.

Approximately 1,032 vehicles are affected by this delivery stop / recall, consisting of 773 in dealer inventory and 259 retailed. Additionally, there are approximately 3,106 vehicles in the pipeline.

Affected vehicles will show the campaign as "Open" when checked either in AIR or ISPA Next. Once the Warranty Vehicle Inquiry system is updated on Saturday, March 3, 2018, it will display the same information. The affected vehicles will be identified with the description: **STOP012917 B710218 Delivery Stop: Emissions Label**

The bulletin will be updated with warranty information when it becomes available.

## CAUSE

An incorrect 2017 emissions label was installed in the vehicle.

## CORRECTION

Replace the current label with the correct 2018 emissions label.

## PROCEDURE

For all affected vehicles:

|  |                                   |
|--|-----------------------------------|
|  | 1. Access engine compartment area |
|--|-----------------------------------|



2. Verify the incorrect MY 2017 emissions label is installed
3. Remove label and clean glue residue from surface area with an approved cleaner
4. Adhere correct MY 2018 emissions label

## PARTS INFORMATION

Use the Vehicle Identification Number (VIN) when referencing ETK.

| Part Number  | Description                    | Quantity |
|--------------|--------------------------------|----------|
| Refer to ETK | Model Year 2018 Emission Label | 1        |

## UPDATE! WARRANTY INFORMATION

Reimbursement for this Delivery Stop will be via normal claim entry utilizing the following information:

|                     |                   |  |
|---------------------|-------------------|--|
| <b>Defect Code:</b> | <b>0071450200</b> |  |
|---------------------|-------------------|--|

**Completion before vehicle delivery to the customer or the vehicle is already in the workshop**

| Labor Operation: | Labor Allowance: | Description:                            |
|------------------|------------------|-----------------------------------------|
| 00 66 540        | 3 FRU            | Replace the emissions label (Plus work) |

Or:

**Completion after vehicle delivery to the customer**

| Labor Operation: | Labor Allowance: | Description:                            |
|------------------|------------------|-----------------------------------------|
| 00 66 027        | 5 FRU            | Replace the emissions label (Main work) |

Posted: Friday, March 9, 2018

## ATTACHMENTS

View PDF attachment [B710218 Delivery Stop Legal](#).

[ Copyright ©2018 BMW of North America, Inc. ]

**Please be reminded that it is a violation of Federal law for you to sell, lease or deliver any vehicle covered by this notification until the delivery stop repair has been performed. This means that centers may not legally deliver new motor vehicles to a consumer until it is fixed or use/sell replacement equipment/parts subject to a delivery stop. Note also that substantial civil penalties apply to violations of this law.**

**Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a delivery stop until the repair is completed.**