



SI M12 06 18
Engine Electrical Systems

March 2018
Technical Service

JCW ENGINE TUNING KIT SHOULD NOT BE PROGRAM WITH ISTA 4.10.1X

MODEL

(F54 (Cooper Clubman))	F55 (Cooper Hardtop 4 door)	F56 (Cooper Hardtop 2 door)	F57 (Cooper Convertible)
F60(Cooper Countryman)			

Produced with the B46M engine and equipped with the JCW Tuning Kit (option code NPOW).

SITUATION

Vehicles with the John Cooper Works (JCW) Tuning Kit should not be programmed with **ISTA 4.10.1x**.

CAUSE

A software error in the following I-level:

- **F056-18-03-511**

CORRECTION

The software correction will be implemented in **ISTA 4.10.2x** which is expected late March.2018.

[Copyright ©2018 BMW of North America, Inc.]