

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

PRODUCT INFORMATION BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	PIB #
4/12/2018	2018	511

MODEL

Bay Star Sport	☐	Ventana	☐	Essex	☒
Bay Star	☐	Dutch Star	☐	King Aire	☒
Canyon Star	☐	Mountain Aire	☒	New Aire	☒
Ventana LE	☐	London Aire	☒	Other	☐

PRODUCT INFORMATION

Certain Dash Xite Radio USB Inputs may have been spliced without the shield of the cable properly attached. If affected, the USB ports may not be active as the USB input to the Xite Infotainment center. The affected USB input is normally located on the driver side console

Non-working USB cables may be replaced with unmodified cables (Newmar part# 110664) to fix the issue.



USB Typical Location on Driver Side



Newmar part # 110664