



SI B64 03 18
Heating and Air Conditioning

March 2018
Technical Service

DELIVERY STOP: REFRIGERANT AIR CONDITIONING

MODEL

F15 (X5 SAV)	F16 (X6 SAV)
--------------	--------------

SITUATION

A Delivery Stop has been issued (effective March 15, 2018) on Model Year 2018 BMW X5 and X6 vehicles produced from January 16 – February 19, 2018. This delivery stop involves the evacuation and refill of the air conditioning system.

Approximately 8 vehicles affected by this stop. There are 5 in dealer inventory and 3 retailed.

Region	Market	Center	Chassis No	Model	Status
C	43	34910 - P & W BMW	0Y00432	F15 (X5)	Retailed
C	46	21181 - Plaza Motor Company	0Y00080	F15 (X5)	Retailed
E	10	34400 - Herb Chambers BMW	0W01456	F15 (X5)	Dealer Inventory
E	12	69000 - Rallye BMW	0Z61151	F16 (X6)	Dealer Inventory
E	14	56738 - Open Road BMW	0Y02413	F15 (X5)	Dealer Inventory
S	22	26726 - BMW of Albany	0Z16091	F15 (X5)	Dealer Inventory
W	32	41903 - South Bay BMW	0W01579	F15 (X5)	Retailed
W	38	28786 - BMW of Anchorage	0Y01961	F15 (X5)	Dealer Inventory

Affected vehicles will show the campaign as “Open” when checked either in Warranty Vehicle Inquiry, AIR or ISPA Next. The affected vehicles will be identified with the description: **STOP012943 B640318 Delivery Stop: Refrigerant Air Conditioning**

This bulletin will be updated with repair, parts and warranty information when it becomes available.

ATTACHMENTS

View PDF attachment [B640318 Delivery Stop Legal](#).

[Copyright ©2018 BMW of North America, Inc.]