

Range Rover
RR Sport
RR Evoque
Discovery
Sport
Discovery

The 'Service
Required' warning
text will not
appear on the
Instrument Cluster
(IC) if a vehicle
has reached its
service point.

This Service Action is currently on sign off which has an updated procedure
which address the SRO time issue.

N118NAS3