

Range Rover
RR Sport
18MY

Customers may report that the interior veneer inserts are scratched.

This may be caused by vehicle protection covers that are installed to the vehicle during transportation. LTB01162 is being published to provide a repair process and recommended polish to remove fine scratches from the veneers.

LTB01162NAS1