

Discovery
17 -18MY

Customers may report the hood is difficult to open.

Engineering is currently investigating a concern where the hood release level is pulled fully, but either one or both of the hood latches does not release. Further pulling of the release cable releases the latches. This may be caused by the hood cable routing. Engineering is requesting that the hood cable routing be inspected prior to removal or replacement of the cable. Specifically checking the radius of the cable bends. Should a customer express a concern, please submit an EPQR with pictures of the cable routing prior to any removal of the cable.

TBC

