

Reference	SSM73794
Models	Range Rover Velar / L560
Title	Reinforcing Plate for Deployable Side Steps
Category	Accessories
Last modified	19-Mar-2018 00:00:00
Symptom	General Accessories
Attachments	VPLYP0370.pdf

Content**Issue:**

Additional reinforcing plate is required when fitting Deployable Side Step accessory parts to Velar.

Cause:

To correct a BIW side step mounting hole eye lidding issue (ref N076v2 - Deployable Side Step Fitment Location Rework), the BIW holes are being enlarged. This will require the fitment of a reinforcing plate.

Action:

The fitting instructions have been updated to show how the plates are fitted. Ensure that the reinforcing plate kit VPLYP0370 is ordered prior to fitting the above accessory.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.