



# Service Bulletin

File in Section: -

Bulletin No.: 18-NA-062

Date: March, 2018

## INFORMATION

**Subject:** Information On Drive Mode Select Switch Will Not Switch Drive Modes

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
GMC	Terrain	2018	2018			LH7	

<b>Involved Region or Country</b>	North America, Middle East
<b>Condition</b>	Some customers may comment that the drive mode selector switch will not switch drive modes.
<b>Cause</b>	This condition may be caused by software anomaly.
<b>Information</b>	Updated software has been released to address this condition. If you encounter a vehicle with the above condition, refer to #17337: Emission Recall - Diesel Particulate Matter Sensor Diagnostic Fault. The ECM reprogramming will also include a solution for the latent mode switch concern.

### Parts Information

No parts are required for this repair.

<b>Version</b>	1
<b>Modified</b>	Released February 26, 2018

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION