

Service Bulletin

File in Section:

Bulletin No.: 18-NA-032

Date: February, 2018

TECHNICAL

Subject: Intellibeam/Auto High Beam Function Inoperable

Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
		from	to	from	to	Engine:	
GMC	Terrain	2018	2018			All	All

Involved Region or Country	North America and N.A. Export Regions		
Additional Options (RPOs)	Excluding Auto Control High Beam (RPO TQ5)		
Condition	Some customers may comment that the Intellibeam/Auto high beam function is inoperable when pushing the button on the turn signal switch.		
Cause	This condition can be caused by the incorrect turn signal switch being assembled on the vehicle due to an engineering release concern. Note: This impacts Denali only without the Driver Alert Package, Denali vehicles without TQ5 option.		
Correction	Replace the turn signal switch with the correct part, and inform the customer that their vehicle is not equipped with the Auto high beam feature.		

Service Procedure

If you encounter a vehicle with the above concern, replace the turn signal switch with the correct part. Refer to *Turn Signal Switch Replacement* in SI.

Parts Information

For the correct part number, refer to the latest part number listed in the parts catalog with the VIN filter on.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
7442380	Turn Signal Switch Replacement	Use Published Labor Operation Time

Version	1
Modified	Released February 1, 2018



