



# Service Bulletin

File in Section: -

Bulletin No.: 18-NA-057

Date: February, 2018

## INFORMATION

**Subject:** Information on False DTCs Set - DTC B0010, B124B, B1265 and/or B127B Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Sonic	2018	2018				
	Trax						
	Tracker						
GMC	Terrain						

<b>Involved Region or Country</b>	North America, Middle East, South America
<b>Additional Options (RPOs)</b>	IOR
<b>Condition</b>	<p>When performing diagnostics on the infotainment system, some technicians may find one or more of the following DTCs set in the radio:</p> <ul style="list-style-type: none"> <li>• B0010 00: Reverse Gear Status Not Plausible set in history</li> <li>• B124B: USB 1 Circuit set current or in history</li> <li>• B1265 04: Switched 14 V Open Circuit set current or in history</li> <li>• B127B: Rear Camera Input Signal set in history</li> </ul>
<b>Information</b>	<p><b>Do not</b> replace any components for these DTCs. This condition may be caused by a radio anomaly.</p> <p>If the concern being diagnosed is not related to the DTCs defined above, then they can be ignored.</p>

### Parts Information

No parts are required for this repair.

<b>Version</b>	1
<b>Modified</b>	Released February 21, 2018

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION