

**Subject:**        **Engineering Information — Service Airbag Indicator Illuminated with DTC U0151 Set**

**Attention:**    **Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PI and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to Service Bulletin 04-00-89-053E for more details on the use of Engineering Information bulletins.**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
GMC	Terrain	2018	2018			All	All

Involved Region or Country	North America
Condition	<p><b>Important:</b> If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI.</p> <p>Some customers may comment on the service airbag indicator illuminated.</p> <p>During diagnosis a technician may find DTC U0151 set or stored.</p> <p><b>Important:</b> The airbag system will still attempt deployment if an event occurs.</p>
Cause	GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

**Correction**

If you encounter a vehicle with the above concern, prior to disconnecting battery, pulling fuses, or replacing SDM contact one of the engineers listed below.

**Contact Information**

Engineer Name	Phone Number
Bryan Dennis	(248) 917-1628
Essam Bouni	(248) 321-1719

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).  
If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

**Warranty Information**

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
2881928*	Engineering Information — Service Airbag Indicator Illuminated with DTC U0151 Set	0.3 hr
* This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		

Version	1
Modified	Released February 08, 2018