



Service Bulletin

File in Section: -

Bulletin No.: 17-NA-190

Date: March, 2018

INFORMATION

Subject: Diagnostic Tip for EBCM DTC U0420 - Invalid Data Received from Power Steering Control Module

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	LaCrosse	2017	2018				
Chevrolet	Malibu (VIN Z)	2016	2016				
Chevrolet	Malibu	2017	2018				

Involved Region or Country	North America, Israel
Condition	During diagnosis technicians may find EBCM DTC U0420 – invalid data received from power steering control module, present or stored in history.
Cause	This condition may be due to a power moding issue where the entire vehicle systems are not on-line. Note: This typically happens during remote start of the vehicle.
Correction	NO repairs should be made.

Version	2
Modified	March 21, 2018 – Added the 2018 Model Year.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION