




Service Bulletin

File in Section: -
 Bulletin No.: 17-NA-238
 Date: March, 2018


TECHNICAL

Subject: Wi-Fi Hotspot and/or Data Sharing Feature Not Working Once it is Turned On

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Sonic, Trax	2018	2018				
GMC	Terrain						

Involved Region or Country	North America and N.A. Export Regions
Additional Options (RPOs)	Equipped with RADIO-INFOTAINMENT SYSTEM - 3.X LOW HMI, MIDLEVEL CONNECTIVITY 3.X (RPO IOR)
Condition	<p>Some customers may comment that the Wi-Fi hotspot is turned on but the connected device(s) does not work.</p> 

4846535

	 <p style="text-align: right;">4846537</p> <p>There are two settings icons that have to be toggled (switched) “on” to “green” to enable Wi-Fi: hotspot and share hotspot data. Note: The Hot Spot feature in the vehicle comes in the off state from the factory.</p>
Cause	This is design intent for Radios with software level prior to 131.155.
Correction	<p>Note: Radios built with software level 131.155 or higher have both switches on by default.</p> <p>Radios with software level prior to 131.155 will need to toggle BOTH switches on, the Wi-Fi hotspot and hotspot data on the display.</p>

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3480568*	Syncing WIFI Hotspot	0.2 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	3
Modified	<p>November 16, 2017 – Added a Note, updated the Correction and changed the Warranty statement.</p> <p>March 08, 2018 – Added software level breakpoint.</p>

