

Subject: Engineering Information – A/C Blows Warm After Driving, Blows Warm Intermittently or Inoperative

This PI has been revised to end the need of information from the field. Please discard PIE0434A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2017	2017			All	All
GMC	Canyon	2017	2017			All	All

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released September 28, 2017 October 06, 2017 – Added a Note in the Warranty Information. March 08, 2018 — Ended the need of information from the field.