



Preliminary Information

PIT5611 Service airbag indicator illuminated with DTC U0151

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	Terrain	2018	All	All	All	All
Involved Region or Country:		North America				
Additional RPO/s:		None				
Condition:		Some customers may comment on the service airbag indicator illuminated. During diagnosis a technician may find DTC U0151 set, loss of communication to the SDM.				
Cause:		Software anomaly				

Correction:

Remove and reinstall the SDM fuse (hard power cycle).
Verify the correction.
Inform the customer that engineering is working on a solution.

Warranty Information

Labor Operation:	Description:	Labor Time:
6480508	Remove and reinstall the SDM fuse	0.3 hrs.

Version History

Version	1
	Created 04/27/2018