



Preliminary Information

PIT5612 Sunroof and or Sunshade Inoperative

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Equinox	2018	All	All	All	All
GMC	Terrain	2018	All	All	All	All
Involved Region or Country:		North America				
Additional RPO/s:		C3U				
Condition:		Sunroof and or Sunshade become inoperative				
Cause:		Sunroof programming loses initialization				

Correction:

Before replacing any parts perform Sunroof Motor/Actuator Initialization/Teach Process found in Service Information. If returns the system to operation return vehicle to customer. If not follow diagnostic steps. Engineering is investigating this concern.

Warranty Information

Labor Operation:	Description:	Labor Time:
6080278	Reinitialize Sunroof	0.3 hrs

Version History

Version	1.0
	Created 04/30/2018

