



Service Bulletin

File in Section: -

Bulletin No.: 17-NA-269

Date: April, 2018

TECHNICAL

Subject: Rear Camera Screen Bright at Night

Attention: This Bulletin replaces PIT5573 and PIT5592. Please discard PIT5573 and PIT5592.

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado, Suburban, Tahoe	2017	2018	SOP	June 12, 2017		
GMC	Sierra, Yukon Models				March 18, 2018		
Chevrolet	Colorado	2018	2019		January 10, 2018		
	S10 (Export)				TrailBlazer (Export)		
GMC	Canyon		2018	March 18, 2018			

Involved Region or Country	North America and N.A. Export Regions
Additional Options (RPOs)	Equipped with RADIO-INFOTAINMENT SYSTEM - UPLEVEL HMI, ENHANCED CONNECTIVITY and RADIO-INFOTAINMENT SYSTEM - UPLEVEL HMI, ENHANCED CONNECTIVITY, EMBEDDED NAVIGATION (RPOs IO5, IO6) WITHOUT RPO U42
Condition	Some customers may comment that the rear camera display is too bright at night.
Cause	This condition may be caused by a software anomaly.
Correction	An updated calibration has been released to address this condition. Reprogram the A22 Radio Controls with the latest calibrations available in TIS2web.

Service Procedure

Refer to *Radio Control Programming and Setup* in SI.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2881278*	A22 Radio Control Reprogramming with SPS	0.3 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	4
Modified	Revised Sept. 13, 2017 – Added the 2018 Model Year. Revised November 22, 2017 – Revising to add Breakpoint. Revised April 18, 2018 – Updated Brand, Model, Model Year and Breakpoint including information under Cause and Correction.

