



Service Bulletin

File in Section: -

Bulletin No.: 18-NA-126

Date: April, 2018

INFORMATION

Subject: Information on Body Control Module (BCM) Replacement

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave, Envision	2018	2018				
Cadillac	XT5						
Chevrolet	Equinox, Traverse						
GMC	Acadia, Terrain						



Involved Region or Country	North America and NA Export vehicles
-----------------------------------	--------------------------------------

The purpose of this bulletin is to notify the dealership personal and technicians when replacing the body control module (BCM), that a 2nd design BCM was released that is NOT interchangeable with the 1st design BCM.



5044016

Technicians need to inspect the label on the module for an indication of (GEN III (R)) as shown in the illustration above.

Group	H	Part Description
<u>02.560</u>		<u>MODULE,BODY CONT(LA BELED GEN III R) (Service Lane Part)</u> 
<u>02.560</u>		<u>MODULE,BODY CONT(NOT LABELED GEN III R)(ACDelco #13594646) (Service Lane Part)</u> 

5044015

Note: The electronic parts catalog (EPC) also identifies the 2nd design as labeled GEN III (R) and is listed it in the Part Description, as shown in the illustration above.

Note: If you are doing a programming event on a new part and see possible wrong part error code it may be because the wrong service part was picked.

Version	1
Modified	Released April 20, 2018

