



HYUNDAI Technical Service Bulletin

GROUP

Electrical

NUMBER

18-BE-006

DATE

APRIL, 2018

MODEL(S)

DH, LFa

SUBJECT:

RADIO SWITCHES ON ITS OWN

Description: This bulletin describes the procedure to repair a condition with the radio changing bands/switching modes between AM>FM>SXM (intermittently) on its own.



Applicable Vehicles:

- 2015-16MY Sonata (LFa) – Non Hybrid
- 2015-16MY Genesis (DH) Non-DIS

Parts Information:

PART DESCRIPTION	PART
<p align="center">SD Card (8" Touchscreen Navigation Vehicles)</p>	

Warranty Information: Normal warranty applies where applicable.

Service Procedure: Please refer to TSB # 16-BE-005-2 for the procedure to perform the software update installation for the AVN system.