

Audi of America, Inc.



<MONTH YEAR>

<CUSTOMER NAME>

<CUSTOMER ADDRESS>

<CUSTOMER CITY STATE ZIPCODE>

This notice applies to your vehicle: <VIN>

**Subject: Extended Warranty Coverage for Natural Vacuum Leak Detection (NVLD)
Pressure Switch**

Certain 2013-2015 Model Year Audi RS5 Coupe/Cabriolet Gasoline Engine Vehicles

Dear Audi Owner:

This notice is sent in accordance with the United States Environmental Protection Agency and the California Air Resources Board regulatory requirements.

Audi has determined that, in some vehicles, it is possible for the natural vacuum leak detection (NVLD) pressure switch to become contaminated with dust, causing the Malfunction Indicator Lamp (MIL) on the instrument cluster to illuminate due to the presence of specific fault codes caused by this component. While this condition causes no impact to vehicle tailpipe emissions, the presence of a MIL-on condition may cause your vehicle to fail an IM (emissions) test.

Because of this, Audi is extending warranty coverage for the NVLD pressure switch in your vehicle (under specific conditions) to 10 years or 120,000 miles, whichever occurs first, from the vehicle's original in-service date.

Warranty Extension Coverage/Limitations


If the MIL in your vehicle comes on and stays on while your vehicle is within the time and mileage limits of this warranty extension, at no cost to you, an authorized Audi dealer will perform a diagnosis to determine if the light is on due to a faulty NVLD pressure switch issue as described above.

- If diagnosis confirms that your vehicle has the issue, the repair will be performed at no cost to you.
- If diagnosis reveals that your vehicle has an unrelated issue(s), any necessary repairs will not be covered under this warranty extension. Your dealer will advise you what the associated repair cost(s) will be.

What you should do:

- Ensure all vehicle drivers have read the vehicle owner's manual so they are familiar with how the emissions system and associated warning lights (including the MIL) work. In some locales, an illuminated Malfunction Indicator Lamp could cause your vehicle to fail an emissions inspection, and your vehicle registration application could be denied.
- Please be aware that other conditions (unrelated to the issue described in this letter) may cause the MIL in your vehicle to illuminate. Customers should be prepared to cover diagnosis and repair costs associated with these other, unrelated conditions.

Audi of America, Inc.
3800 Hamlin Road
Auburn Hills, MI 48326
+1 800 253 2834
www.audiusa.com



- Please keep this letter with your Warranty booklet for future reference, and deliver it to any new owner, along with the owner's manual. Should you ever sell the vehicle, this warranty extension is fully transferable to subsequent owners.

Additional Information

- The vehicle's original in-service date is defined as the date the vehicle was delivered to either the original purchaser or the original lessee; or if the vehicle was first placed in service as a "demonstrator" or "company" car, on the date such vehicle was first placed in service.
- The warranty and maintenance information that came with your vehicle contains information on the limited warranties applicable to your vehicle. Please read these limited warranties carefully to determine your warranty rights and obligations, as this information also applies to the coverage provided to you in this warranty extension.
- Damage or malfunctions caused by outside influence, such as damage due to an accident, or vehicle misuse or neglect, and repairs that are necessary for proper diagnosis of these conditions or required to bring the vehicle up to factory specifications are not covered by this warranty extension.
- If you are the lessor and registered owner of the vehicle identified in this warranty extension, please forward this information immediately via first-class mail to the lessee within ten (10) days of receipt of this notification.
- If you have changed your address or have sold the vehicle, please fill out the enclosed prepaid owner reply card and mail it to us so we can update our records.
- If you have previously paid for replacement of a faulty NVLD pressure switch due to the issue described in this letter, the enclosed form explains how to request reimbursement. We would be pleased to review your reimbursement request.

If you should have any questions about this communication, please reach out to Audi Customer Experience at 1-800-253-2834 or via our "Contact Us" page at www.audiusa.com.

We are pleased to offer this extended emissions warranty and hope that you will continue to be a member of the Audi family.

Sincerely,

Audi Service & Quality