

NEW DIAGNOSTIC SOFTWARE AVAILABLE FOR DOWNLOAD



Notice Information

Ref	6107
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor
Subject:	Service/Technical

TOL NOTICE (US&CAN) – February 27, 2018

New Diagnostic Software Available for Download

Diagnostic software version 2018-4 is now available to download. Dealers should download this update from your Triumph Diagnostic Software page under the Service/Technical menu and begin using immediately.

- Please ensure all new bikes have the latest software downloaded at PDI.
- Please ensure all bikes being serviced have the latest software downloaded.
- Please ensure all relevant staff are informed of this update.

PASSWORD: No change to password: (case sensitive) Cafe1902

SUMMARY OF CHANGES:

- Keyless ECM download button added to download section
 - Build Data screen added to Immobilizer Diagnostics for models fitted with a keyless ECM (Speed Triple RS)
 - Immobilizer Systems pairings implemented for models fitted with a keyless ECM (Speed Triple RS)
 - Improved robustness of Chassis ECM/Keyless ECM calibration downloads (no changes to dealer process)
 - Function test added to recalibrate windscreen motor – Tiger 1200 models
- 1 New Software Functionality:**
 - 9 x new **engine calibrations** for the new 2018 Speed Triple S
 - 5 x new **engine calibrations** for the new 2018 Speed Triple RS
 - 2 New Calibrations:**
 - 2 x new TFT **instrument calibrations** for the new 2018 Speed Triple S
 - 3 x new TFT **instrument calibrations** for the new 2018 Speed Triple RS
 - 3 x new keyless **ECM calibrations** for the new 2018 Speed Triple RS
 - 3 Replacement Engine ECM Calibrations:**
 - 5 x replacement calibrations for Bonneville Speedmaster
 - 12 x replacement calibrations for Bonneville T120/T120 Black

4	Replacement Chassis ECM Calibrations:	None
5	Replacement Instrument ECM Calibrations:	None
6	Replacement Keyless ECM Calibrations:	None
7	New ECU Unlock Codes:	New 2018 Speed Triple S and Speed Triple RS - 21796885
8	Calibration Description Corrections:	None
9	Bug Fix(es):	EMRF and Autoscan templates improved to resolve display issues seen when special characters are used (Note: Internet Explorer should be used where possible to view reports)

If you have any questions, please contact Triumph 24/7 Customer Support at (888) 284-6288.