

SSM  
47006

All 2016 F-650 and F-750 vehicles built before 1-Apr-2016 requiring replacement of the reductant pump control module also requires replacement of the 14407 wiring harness which is included with the module service part. The current level service replacement module is not compatible with the harness on early build vehicles.