
Reference	SSM73738
Models	Range Rover Sport / L494
Title	16MY Range Rover Sport 3.0L TDV6 DPF Efficiency Below Threshold, DTC P2002
Category	Engine
Last modified	29-Jan-2018 00:00:00
Symptom	403000 Exhaust System Concerns

Content Issue: The customer may experience a Check Engine Light on the instrument cluster and DTC, P2002, stored in the PCM.

Cause: This issue is currently under investigation.

Action: Follow TOPIx steps of diagnosis for this DTC. Should a vehicle require a replacement to rectify this concern, please replace both the Diesel Particulate Filter & Differential Pressure Sensor concurrently. Submit an EPQR with your parts manager information (name, address, phone number, and email). Engineering is seeking parts to further the investigation.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.