

Latest Vehicle Concern Fixes



Vehicle	Customer Concern	Details and Status	Publication
Discovery 17MY onwards	A Customer may report difficulty in opening the hood.	A few reports have been received regarding difficulty opening the hood panel when the release level is pulled. The reports suggest that the cable is too long for the application and does not pull far enough to release the hood latches. This concern is currently being investigated. Should this concern be found please submit an EPQR for the vehicle to aid in the investigation.	Under Investigation
F-TYPE Coupe	A Customer may report the load space cover is warping.	A Customer may find the Parcel Shelf (load space cover) is distorting, lowering in the center. This concern is currently under investigation. If you find any cases of this concern please submit an EPQR with picture showing the amount of distortion.	Under Investigation

