



Harley-Davidson Motor Company  
3700 West Juneau Ave., PO Box 653, Milwaukee, WI 53201

**Technical Services Call Task Description:** 2018 Softail Fender Torque Repair

**Call Task #:** CT2018-005

**Communication Start Date:** 03/22/18 – 04/12/18

**Motorcycles Affected:**

#	Make	Model	Model Year
1	Harley-Davidson	SOFTAIL	2018

**Summary of Issue:** (2000 characters limit)

Technical Service Call Task: During a fender assembly process some rear fenders may have been under torqued at the plant. Follow the steps in call task to repair MY2018 Softail Rear Fender Fasteners. Torque 28-37 Nm (21-27 ft-lbs.) as instructed in the service manual.

**Components Affected:** (Include part numbers, if known)

P/N SCREW – 10200521 or SCREW – 10200033 (FLSB)

**Follow-up Actions:** (Include any additional actions required by dealer, Technical Services, or other, if any)

Complete a warranty claim for the repair.