



EMISSION RECALL

**2017-2018 CMX300/A, CMX500/A - EVAP CANISTER
CHARGE HOSE REPLACEMENT**

AFFECTED UNITS

2017 CMX300 (AC type)	All
2017 CMX300A (AC type)	All
2018 CMX300 (AC type)	VIN MLHNC531*J5100001 through MLHNC531*J5100310
2018 CMX300A (AC type)	VIN MLHNC535*J5100001 through MLHNC535*J5100448
2017 CMX500 (AC type)	All
2017 CMX500A (AC type)	All
2018 CMX500 (AC type)	VIN MLHPC561*J5100001 through MLHPC561*J5100346
2018 CMX500A (AC type)	VIN MLHPC565*J5100001 through MLHPC565*J5100575

* Denotes check digit

AC type: (50-State type, meets CA Emission)

STOP SALE NOTICE

Honda is launching an EMISSION RECALL on model year **2017 through 2018 CMX300 (AC type*) and CMX500 (AC type*)** motorcycles to replace a defective Evaporative Emission Canister Charge Hose. The fuel vapor permeation of the Canister Charge Hose exceeds the EPA emission regulation.

Effective immediately, YOU MUST NOT SELL any affected (new or used) 2017 - 2018 CMX300 (AC type*) or CMX500 (AC type*) motorcycle until it is repaired according the associated Service Bulletins.

*AC type: 50-State model (meets CA Emission)

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your Honda. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your Honda, or that your Honda has the condition described. To determine whether this information applies, contact an authorized Honda dealer.