



Preliminary Information

PIP5568 Service Engine Soon Light Comes on With All 4 Camshaft Position System Performance DTC's P0011, P0014, P0021 and P0024 Setting.

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|----------------------------|--|--------------|------|-----|------------------|----------------|
| | | | from | to | | |
| Buick | Enclave | 2018 | All | All | 3.6 LFY | All |
| Buick | LaCrosse | 2017 - 2018 | All | All | 3.6 LGX | All |
| Buick | Regal | 2018 | All | All | 3.6 LGX | All |
| Cadillac | ATS | 2016 - 2018 | All | All | 3.6 LGX | All |
| Cadillac | CT6 | 2016 - 2018 | All | All | 3.0 LGW, 3.6 LGX | All |
| Cadillac | CTS | 2016 - 2018 | All | All | 3.6 LGX | All |
| Cadillac | XT5 | 2017 - 2018 | All | All | 3.6 LGX | All |
| Chevrolet | Traverse | 2018 | All | All | 3.6 LFY | All |
| Involved Region or Country | North America | | | | | |
| Condition | Some customers may come in with a MIL/SES illuminated and no drivability concerns. | | | | | |
| Cause | Tech will find P0011, P0014, P021, and P0024 ALL set in the ECM. | | | | | |

Correction:

If All these codes are found, check to see if TSB [17-NA-317](#) (LFY equipped vehicles only) has been completed and perform that action if it has not been done.

If the bulletin above has been completed or does not apply, clear the codes and return the vehicle to the customer.

At this time the cause for this concern is under investigation.

Please do not replace any parts for the concern at this time.

NOTE: We will update the PI or create a bulletin to replace this PI when more information becomes available.

Version History

| | |
|----------|---------------------|
| Version | 1 |
| Modified | Created on 5/7/2018 |

