

Classification:

Reference:

 COPYRIGHT© NISSAN NORTH AMERICA, INC.  
 Date:

EL18-008

ITB18-018

May 1, 2018

## 2018 Q70; INTOUCH APP HORN/LIGHT ACTIVATION FEATURE DOES NOT TURN ON HORN/LIGHT

**APPLIED VEHICLES:**            2018 Q70 (Y51)  
    2018 Q70 Hybrid (Y51)

### IF YOU CONFIRM

On a vehicle that is equipped with "Remote Sound Horn and Flash Lights", and the Infiniti InTouch App has been down-loaded to the customer's smart phone:

- The vehicle Horn and Lights do not operate when the Horn/Light button is selected on the InTouch smart phone App.

Or

- The vehicle Lights do not operate when the Light button is selected on the InTouch smart phone App.

And

- The Horn/Light or Light button on the InTouch App displays a green check-mark with a "Success" message on smart phone.




Figure 1

### ACTION

Replace the BCM with the new one listed in the Parts Information.

- Refer to the Electronic Service Manual (ESM), section **ELECTRICAL POWER CONTROL > BODY CONTROL SYSTEM**, for replacement information.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.

**PARTS INFORMATION**

DESCRIPTION	PART NUMBER	QUANTITY
BCM	284B1-5UW0A	1

**CLAIMS INFORMATION**

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace BCM	(1)	RD94AA	ZE	32	(2)

(1) Reference the electronic parts catalog (FAST), and use the BCM Controller Assy (284B1-\*\*\*\*\*) as the Primary Failed Part (PFP).

(2) Reference the current Infiniti Warranty Flat Rate Manual and use the indicated Flat Rate Time (FRT).

