

Please distribute to:
Dealer Principal, Warranty Manager, Service Manager, Parts Manager, Sales Manager

- | | | |
|--|---|--|
| ☐ Freightliner Dealers | ☒ Direct Warranty Customers | ☐ Sales Terms (DTR) |
| ☐ Western Star Dealers | ☐ Export | ☐ Used Product (DTR) |
| ☒ Thomas Built Bus Dealers | ☐ DDC Distributors | ☐ Travel Centers of America/Petro:Lube |
| ☒ FCCC Dealers | | |

IMPORTANT WARRANTY INFORMATIONREF **18-012**

Effective 04/16/2018

Release 04/16/2018

SUBJECT TBB: Pre-Delivery Inspection Form (WAR402) Update

❖ **TBB PDI Form Revised**

Please be aware that DTNA revised engine mounting bolt instructions on the Thomas Built Bus (TBB) Pre-Delivery Inspection (PDI) Form (WAR402).

The following modification was made to the TBB PDI Form (WAR402):

- Section A (Underside) > Engine Mounting Bolts
 - o Check engine mounting bolts for signs of torque seal (EFX and HDX units)
 - o If not present, remove the fasteners and apply torque seal and torque per spec; refer to the installation diagram

The updated form is available for immediate use at *DTNAConnect > Warranty Lit > Other Warranty Documents > Forms*. TBB PDI labor times and records retention policies remain unchanged; see the [DTNA Warranty Manual](#) for more information.

IMPORTANT WARRANTY INFORMATION LETTER

Verify latest version online: Important Warranty Information Letters are available at *DTNAConnect > Warranty Lit > Warranty Letters*.

DISCLAIMER: The information contained in this letter supersedes and supplements any related policies and procedures in the Warranty Manual and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.