



Subject		Market
Rear spoiler Gappoiler Gap		USA
Service Category	Section	
Vehicle Exterior	Exterior Panels/Trim	
Applicability		
2017 - 2018MY IS models– 2018 MY IS models		

APPLICABLE VEHICLES

2017-2018	IS350	2017-2018	IS300
2017	IS200T		

CONDITION

Some vehicles may experience a condition in which the LH or RH rear spoiler exhibits a gap, looseness or separation from trunk lid.

RECOMMENDATIONS

Please document the following during diagnosis and repair of the vehicle and submit a DPR.

1. Take overall photograph showing the location of the gap and looseness or separation between the rear spoiler and the trunk lid.
2. Inspect the installation condition of both side clips while in an assembled condition.
 - Take photograph of the seating condition of clips from inside trunk lid.



Subject	Market
Rear spoiler Gap	USA
Applicability	
2017 - 2018MY IS models	

RECOMMENDATIONS

3. After removal of the rear spoiler take photographs of the following:
 - If there is damage on clips and location of damage on clips.
 - Adhesive condition on both sides of spoiler highlighting the areas of contact or no contact to the body, please refer to the second picture set above for taking the photograph.
4. After replacing the rear spoiler, take an overall photograph showing the location of the gap and looseness or separation between the rear spoiler and trunk lid.

LINK REFERENCES

This Tech Tip does not contain any link references