

FLA COE
FLB COE
> FLD Conventional
> Business Class

FLC 112 Conventional
> Century Class Conventional
> Argosy COE
> Cargo

> Columbia
> Condor
> Coronado
> Business Class M2

**Freightliner
Service Bulletin**

General Information

To address an ongoing field issue with its Drivemaster fan clutch hub bearings, Horton has created an updated bearing pack that should be used to repair the Drivemaster fan clutch.

The new repair kit part number is HOR 994985. It replaces the Super Kit, HOR 994347.

All Horton Drivemaster repair kits with a date code after September 6, 2005 contain the updated bearing pack.

Warranty

Normal warranty applies.