

> FLA COE
> FLB COE
> FLD Conventional

> Business Class
> FLC 112 Conventional
> Century Class Conventional

> Argosy COE
Cargo

Freightliner
Service Bulletin

General Information

Incandescent bulbs are sometimes being replaced with LEDs, which are becoming more popular in the trucking industry. Trucklite has kits available to replace incandescent side marker lights with LEDs.

IMPORTANT: Using LEDs for brake lamps or turn signals may generate fault codes on vehicles equipped with the Eaton® VORAD® EVT-200 or EVT-300 Collision Warning System. Freightliner recommends that LEDs **not** be used for brake lamps or turn signals on vehicles with either warning system. Vehicles without the warning system will not be affected by this problem.

To replace incandescent side marker light bulbs with LEDs, find the correct part numbers in [Table 1](#).

LED Replacement Kit Part Numbers	
Freightliner Incandescent Lamp Part Number	Trucklite LED Part Number
A06-27561-000	TL 21094Y
A06-27561-001	TL 21091Y
A06-27561-002	TL 21090Y
A06-27584-000	TL 21093Y
A06-27584-001	TL 21095Y
A06-27584-002	TL 21092Y
A06-27584-003	TL 21095Y

Table 1, LED Replacement Kit Part Numbers

Parts

Parts are available through the PDCs.

Warranty

This is an informational bulletin only; warranty does not apply.