

FLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 Conventional

Century Class Conventional
Argosy COE
Cargo
Columbia
122SD and Coronado

Business Class M2
Cascadia
108SD/114SD
> New Cascadia

**Freightliner
Service Bulletin**

General Information

The mirror-arm pivot joint on the New Cascadia primary door-mounted mirror assembly is not serviceable. If the clutch bolt (see [Fig. 1](#)) is turned with a wrench, the mirror-arm pivot joint will be compromised, possibly allowing the joint to loosen over time. If a mirror-arm pivot is damaged or defective, the entire mirror assembly must be replaced. For mirror assembly replacement, refer to *New Cascadia Workshop Manual*, **Section 60.03, Subject 100**.



Fig. 1, Mirror-Arm Pivot Clutch Bolt

Warranty

This bulletin is informational only. Warranty does not apply.