

JTB00638NAS1

TECHNICAL BULLETIN

11 MAY 2018



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION**SECTION:**

311-01: Automatic Transmission

SUBJECT/CONCERN:

Transmission Cover Gasket Leak

AFFECTED VEHICLE RANGE:

| MODEL: | MODEL YEAR: | VIN: | ASSEMBLY PLANT: |
|---------------|--------------|----------------|-----------------|
| E-PACE (X540) | 2018 Onwards | Z00001 Onwards | Graz (Austria) |

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

A fluid leak from the transmission, poor shift quality, and/or transmission noise may be evident.

CAUSE:

This may be caused by a transmission cover gasket leak.

ACTION:

Should a customer express this concern, follow the Workshop Procedure below.

PARTS:

| PART NUMBER | DESCRIPTION | QUANTITY |
|-------------|----------------------------------|----------|
| T4A19475 | Automatic transmission cover kit | 1 |
| JDE26444 | Automatic transmission fluid | 1 |

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:**NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

| DESCRIPTION | SRO | TIME (HOURS) | CONDITION CODE | CAUSAL PART |
|---|----------|--------------|----------------|-----------------|
| Automatic transmission cover gasket - Renew - Check and top up transmission fluid | 44.20.28 | 1.0 | D8 | J9C6450/J9C6453 |

 **NOTE:**

Normal Warranty procedures apply.

WORKSHOP PROCEDURE:

- 1 Install a new automatic transmission cover gasket (see TOPlx Workshop Manual section 311-01: Automatic Transmission - Removal and Installation - Transmission Cover).