

E-PACE	A Customer may report the air conditioner is blowing warm air post H100 HVAC software update.	A concern has been identified on specific vehicles within Service Action H100 where after the HVAC module software was updated the PATHFINDER routine did not complete a compressor run-in routine automatically following the HVAC module software download. This will prevent the compressor clutch from operating until the run-in routine is performed. Update Prior to Sale campaign (UPS) H106 has been published to proactively complete the compressor run-in procedure on affected unsold vehicles. Service Action H113 will be published to proactively repair Customer vehicles.	H106NAS1 On Sign-off
--------	---	---	-------------------------