

<b>Reference</b>	SSM72302
<b>Models</b>	F-TYPE / X152 XE / X760 XF / X260 XJ / X351
<b>Title</b>	B1412-96 is being flagged in the Gateway Module
<b>Category</b>	Electrical
<b>Last modified</b>	16-May-2018 00:00:00
<b>Symptom</b>	203000 Basic Electrical
<b>Content</b>	<p><b>Note:</b> This is only applicable to the following vehicles and models years XJ(X351) 13MY onwards F Type(X152) 14MY onwards XE(X760) 16MY onwards. XF(X260) 16MY onwards</p> <p><b><u>Issue</u></b> B1412-96 being flagged in the Gateway Module</p> <p><b><u>Cause</u></b> Under Investigation.</p> <p><b><u>Action</u></b> False log of DTC 1412-96 in the Gateway Module and will not clear due to internal software issues. This will not affect the vehicle performance and is not visible to the customer.</p> <p>If DTC 1412-96 is identified:</p> <ol style="list-style-type: none"> <li>1. Do not replaced the Gateway Module for this DTC.</li> <li>2. Do not replace the Quiescent Relay Box for this DTC.</li> </ol> <p>SDD will be updated in due course.</p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>

